


# Comprehensive Vehicle Appraisal Report

Dealership: Dealer Nine Trade Scan Report

Date of Appraisal: 6/16/2022 Appraised By: dealer Nine

Vehicle Information	
Year	2014
Make	Cadillac
Model	ATS
Trim	4D SEDAN LUXURY
Odometer	117046
VIN:	1G6AH5RX1E0121057
VIN Fraud Check OBD	✓
MMR Price	\$16,150.00
MMR Range	\$13,000.00 - \$19,300.00



Diagnostic Trouble Codes	
B3031 ( History )	Key Decoder Device in Assem Learn Mode
B101E ( History )	Electronic Control Unit Software
U0159 ( Active )	Lost Communication With Parking Assist Control Module
U0140 ( History )	Lost Communication With Body Control Module
P0013 ( Pending )	"B" Camshaft Position - Actuator Circuit/Open Bank 1 b

Repair Cost			
DTC Code	Standard Time	Cost (\$)	
Dtc Code : U0159			
Failed Component : Parking Aid Module			
PARKING ASSIST MONITOR MODULE ( Operation Required : Remove & Replace )	2.3	\$230.00	
Dtc Code : U0140			
Failed Component : Body Control Module			
BODY CONTROL MODULE ( Operation Required : Remove & Replace )	1.0	\$100.00	
Dtc Code : P0013			
Failed Component : Camshaft Position Sensor			
CAMSHAFT POSITION SENSOR ( Operation Required : Remove & Replace )	0.5	\$50.00	

Appraisal Notes

codes

Manheim			Kelley Blue Book		
Above	Average	Below	Fair Purchase Price	Fair Market Range	
			High	Low	
\$19600	\$16200	\$12800	\$21382	\$22764	\$19999

J.D. POWER				Black Book			
	Clean	Average	Rough		Clean	Average	Rough
Trade in				Trade in			
Base	\$13075	\$11575	\$9775	Base	\$14450	\$12550	\$10015
Add/Ded	\$0	\$0	\$0	Add/Ded	\$0	\$0	\$0
Odo.	\$6538	\$6538	\$6538	Odo.	\$4900	\$5475	\$5007
Total	\$19613	\$18113	\$16313	Total	\$19350	\$18025	\$15022


CarDr.com

# To Request a Demo

- 1-800-932-1120
- Support@CarDr.com
- <https://cardr.com/appraisal>



# World's Most Advanced Mobile Diagnostics System



**DTC Codes Detected**




**Increased Profits**







## OEM Level Scans Protect Dealer Profits



Detects  
P, B, C & U Codes




## Patterned Component Failure (PCF)



Possible Components Failed  
+  
Labor Costs



## Built by Dealers for Dealers



Order Parts

